

EXHIBIT C

Allied GM claims - July, 2009

Clim#	Insured's name	YR	Make	Model	Claim amount inc ded	Type of claim fire/Collision/other - if other, specify	O&C (yes or no)	Cause-(defective part - specify)	Add'l info
24C41580	[redacted for privacy]	6	Chevy	Cargo	\$24,221.78	Ftc Fire	Y	broken hose allowed power steering fluid to spray out and ignite on hot engine surface	
26E90246	[redacted for privacy]	5	Chevy	Silverado	\$24,988.50	Ftc Fire	Y	Fire in 00Gr Prix, recall oil leaking onto hot manifold	ho xfile 72-001217
14U35414	[redacted for privacy]	7	Chevy	Tahoe	\$110,805.00	Ftc Fire	Y	dash fire	ho xfile 72-047054 w/sub attny
14R62927	[redacted for privacy]	4	Chevy	K2500	32994.22	Ftc Fire	Y	possible battery cable shorted	w/Sub Attny
9234 PE043341 06/11/09	[redacted for privacy]	6	Chevy	k3500 silverado	nothing to date	ftc fire	Y	blower motor/ resistor block	recent repairs at dealership; additional sums were paid on this claim, to bring the total paid to \$25,575.62.
25A42130	[redacted for privacy]	8	Chevy	3500	36,207.62	ftc fire	Y	engine compartment fire	styer
24C32934	[redacted for privacy]	6	Chevy	Corvette	41282.09	ftc fire	Y	engine compartment fire	styer
					\$270,499.21				